

# CERTIFIED TESTIMONIAL

Type of user Excavating Company File Reference No. 11020  
Type of application Drott 40 Cruz-Air Back Hoe Date of testimonial June 10, 1978  
Jonco product used Engine Treatment Locale Niverville, Manitoba

Dear Bob,

Early April we purchased two cans of Treatment for our Drott 40 Cruz-Air Back Hoe. The engine, a Detroit Diesel 453, had about 700 hours on it. We noticed a remarkable change in the operating temperature of the engine after about 60 hours of operation. Before it would run up to 190 & 195°F. with a 180°F thermostat. Since the change we have never seen it over 180°F which is where the thermostat opens.

Another startling change was in the acceleration, which runs through the engine governor. This change came at about 6 hours after treatment. The governor freed up so much and so quickly, that we thought something had broken. We actually stopped and checked the Drott out to see if something was wrong. Today with over 1000 hours it is still operating fine.

Thanks for introducing this product to us.

Owner

## CERTIFICATION

I hereby certify that the above excerpts taken from original testimonial file reference No. \_\_\_\_\_

11020

are true and correct.

May 4 1983

*Gregory A. (Harris)*

Harris

NOTARY OR DEPUTY

COUNTY & SEAL

